



1- Glass Cut



4- Glass Tempered



5- Glass Cleaned



6- Glass in Laminating Line



8- Glass into Flat Pressing Machine



7- PVB Put between Two Glasses



9- Glass out of Flat Pressing Machine



10- Glass into Autoclave for 7 Hours